
cope



PATENT

Certificate
JAN 1 8 2005
of Correction

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.:

6.812.905 B2

Issue Date:

November 2, 2004

Applicant:

Thomas et al.

Application No:

09/998,873

Filed:

October 31, 2001

Title:

INTEGRATED ACTIVE ANTENNA FOR MULTI-CARRIER

APPLICATIONS

Art Unit:

2821

Confirmation No:

7709

Examiner:

Tho Phan

Atty. Docket No:

ANCO-25US

Cincinnati, Ohio 45202

January 4, 2005

Certificates of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. 1.322(a))

Attached, in duplicate, is Form PTO-1050 (Substitute Form PTO76-22), with at least one copy being suitable for printing.

The exact page and line number where the errors are shown correctly in the application file are:

Column 1, line 52, reads "...around ten wafts." and should read -...around ten watts. - .

Column 6, line 28, claim 12, reads "...support structure, end an antenna..." and should read - ...support structure, and an antenna... - .

Column 6, line 62, claim 17, reads "...between said the first RF transceiver and..." and should read – ...between the said first RF transceiver... – .

It is noted that errors appear in this patent of typographical nature or character, as more fully described above. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

Please send the certificate to the undersigned. If any other charges or credits are necessary to complete this communication, please apply them to Deposit Account 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P..

Kurt A. Summe

Reg. No. 36,023

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati OH 45202 (513) 241-2324 (513) 421-6234 facsimile

Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,812,905 62_

Page 1 of 1

DATED

: November 2, 2004

INVENTOR(S): Thomas et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 52, reads "...around ten wafts." and should read - ...around ten watts. - .

Column 6

Line 28, claim 12, reads "...support structure, end an antenna..." and should read - ...support structure, and an antenna... - .

Line 62, claim 17, reads "...between said the first RF transceiver and..." and should read -...between the said first RF transceiver... - .

MAILING ADDRESS OF SENDER:

PATENT NO. 6,812,905 No. of add'I copies @ 50¢ per page

WOOD, HERRON & EVANS, L.L.P. 2700 Carew Tower, 441 Vine Street Cincinnati, Ohio 45202 SUBSTITUTE FORM PT076-22

Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

: 6,812,905 B2 PATENT NO.

Page 1 of 1

DATED

: November 2, 2004

INVENTOR(S): Thomas et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 52, reads "...around ten wafts." and should read - ...around ten watts. - .

Column 6

Line 28, claim 12, reads "...support structure, end an antenna..." and should read - ...support structure, and an antenna... - .

Line 62, claim 17, reads "...between said the first RF transceiver and..." and should read -...between the said first RF transceiver ... - .

MAILING ADDRESS OF SENDER:

PATENT NO. 6,812,905 · No. of add'I copies @ 50¢ per page

WOOD, HERRON & EVANS, L.L.P. 2700 Carew Tower, 441 Vine Street Cincinnati, Ohio 45202 SUBSTITUTE FORM PT076-22